


Town of Danvers




Emergency Response to November 22, 2006 Explosion Lessons Learned





Seismograph from Weston Observatory



File: WES.BHZ.NE

4



November 22, 2006 Event

- 2:46 A.M.
- Explosion heard throughout Town and North Shore
- 100⁺ structures heavily damaged or destroyed



Immediate Response

- Evacuate 400⁺ residents
- Search for injured / dead
- Attack fire
- Set up shelter



Secondary Response

- Establish ISU
- Assess priorities and assign responsibilities
- Update meetings at 1 hour, 2 hour, etc. intervals

Initial Priorities

- Fire Control
- Public Health Air and water quality
- Safety of structures
- Site security
- Shelter
- Establish EOC and designate PIO

Assigned Responsibilities

- Fire control *Fire Chief & Deputy*
- Structural safety *Building Inspector*
- Public Health Health Director / EPA
- Site security Police Chief
- Shelter Public Works/Health Director
- Establish EOC & PIO Town Manager



- Be prepared; have a plan.
- Take responsibility.
- Communicate at <u>all</u> levels
- <u>Delegate</u> It's a team effort.



- Stay calm.
- Take care of yourself & key staff.
 - Could have done better.
- Recognize peoples' efforts.
- Critique what worked and what didn't.

- Assign key staff roles in advance: DPW; Financial management; P/F; Health; Volunteer boards
- Fully utilize technology: Connect CTY; Twitter; Town website; Web EOC
- Public Safety Dispatch overloaded working to modernize and regionalize



- Improve coordination with outside agencies: SFM; CSB; ATF; State Police
- Find a role for Board of Selectmen







